

LUESA

Customer Service Center & Office Renovation

Weekly Update – October 16, 2015

Gensler





Meetings & Milestones

This Week:

- ✓ GWB Hanging Continued on 1st and 2nd Floors
- ✓ Hard Ceiling Framing Continued
- ✓ MEPF Overhead Rough-In Continued
- √ 10/13/15 Subcontractor Meeting
- √ 10/15/15 O/A/GC Meeting
- ✓ Electrical Rough-In on Upper Floors Continued
- ✓ Drywall Point Up and Prime Painting on Upper Floors Continued

Next Week:

- **➢** GWB Hanging Continues on 1st and 2nd Floors
- MEPF Overhead Rough-In Continues
- > 10/20/15 Subcontractor Meeting
- > 10/20/15 Owner Low Voltage Vendor Coordination Meeting
- > 10/22/15 O/A/GC Meeting
- Electrical Rough-In on Upper Floors Continues
- > Dryfall Paint Open Ceiling in 1st Floor Customer Service Area
- Drywall Point Up and Prime Painting on Upper Floors Continues






1st Floor Overhead MEPF Rough-In & Wall Hanging In Progress





1st Floor One-Sided Wall Hanging and Insulating In Progress





Floors 2-4 Prime Painting In Progress





2nd Floor Egress Corridor GWB Hanging In Progress

RODGERS Leeper



Conclusion of Weekly Update 10/16/15

Thank You.